

Pneumatic Test - Incident

Incident happened in a non-ExxonMobil facility in Brazil during a pneumatic test of the tank associated piping. A blind was NOT installed to isolate the piping – only block valves were closed.

The tank “lifted off” and was found on top of the unit!



26 1 2006



26 1 2006



26 1 2006



26 1 2006